

SECTION CORNER RECORD


MARION COUNTY, INDIANA

Sec. 4 Twp. 16 Range 5



INST. - Leary      ROD. - \_\_\_\_\_

TYPE of MARKER: 5/8" steel rebar COND. of MARKER: Good

A traverse was run by the MCSO to reproduce the Schneider Survey. This corner falls 0.39 feet South and 7.43 feet East of the previous location per MCSO (steel rebar  $\approx$  al.cap)



Section 32-17-5



W 1/2 NE 1/4  
Sec. 4-16-5

E 1/2 NE 1/4  
Section 4-16-5

SX 650411

[illegible]